



Notes:

- Face frames with 1/4" MDF using countersunk flat head self tapping screws. No glue
- Screws should be placed at least every 1'. Add more as necessary
- Facing covers front and bottom of frames with fronts capping bottoms
- Attach shackle plates using 1/4" rated hex head bolts, washers, and nuts.
- All fasteners used must be aluminum, stainless steel, or zinc coated steel to prevent galvanic corrosion

Ohio Light Opera	
Portal System Facing Layouts	
Header B Facing and Hardware	
Drafted By: Samantha Miller	PF 7
Plot Date: 4/28/15	Scale: 1" = 1'